

## **UNI-TREND UT275**



Earth fault current clamp meter - LED display up to 1000 accounts - Measurement of leakage current up to 30A - Earth resistance measurement up to 1000? - Auto calibration | Auto range - Resistance limit alarm

- UNI-T
- CAT III ground current clamp meter 300V
- LCD display up to 10000 accounts
- Leakage current measurement of 30A
- Measurement of insulation resistance to ground up to 1000?
- Auto range
- Auto calibration
- Data blocking
- Data storage
- Resistance limit alarm
- Low battery indicator
- Automatic shutdown