

## **UNI-TREND UT332+**



Environmental Condition Meter - Temperature and humidity measurement - Lightweight, cost-effective design with intuitive interface - Automatic shutdown - Dew point and thermal sensation - USB connection to PC software

- UNI-T
- Temperature and humidity meter
- Backlit LCD display
- Temperature measurement range between -20°C~70°C
- Dew point and Thermal measurement
- Humidity measurement range between 0~100%RH
- Automatic shutdown
- USB connection to PC software